



Department of Energy

ROCKY FLATS FIELD OFFICE
P.O. BOX 928
GOLDEN COLORADO 80402 0928

MAY 17 1995

95-DOE-08380

Mr Martin Hestmark
U S Environmental Protection Agency, Region VIII
ATTN Rocky Flats Project Manager, 8HWM-RI
999 18th Street, Suite 500, 8WM-C
Denver, Colorado 80202-2405

Mr Joe Schieffelin, Unit Leader
Hazardous Waste Facilities
Colorado Department of Public Health and Environment
4300 Cherry Creek Drive South
Denver, Colorado 80222-1530


ADMIN RECORD

Gentlemen

We are transmitting responses to you on the Operable Unit (OU) 2 (902 Pad, Mound and East Trenches) Technical Memorandum (TM) 1 to the Corrective Measures Study/Feasibility Study (CMS/FS) TM 1 is entitled Development of Corrective/Remedial Action Objectives We are responding to your comments dated March 22, 1995 These comments will be incorporated into TM 2, "Initial Screening of Remedial Technologies and Identification of Remedial Alternatives"

If you have any questions, please contact Bill Fitch at 966-4013

Sincerely,


Steven W Slaten
IAG Project Coordinator
Environmental Restoration

Enclosure

cc w/o Enclosure
H Belencan, EM-452, HQ
J Ahlquist, EM-452 HQ
C Gesalman, EM-453, HQ
B Fitch, ER, RFFO
E Dille, SAIC
A Primrose EG&G
P Laurin, EG&G
Administrative Records

**DOCUMENT CLASSIFICATION
REVIEW WAIVER PER
CLASSIFICATION OFFICE**